EAST Search History

EAST Search History (Interference)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	8	(bath or reservoir) and (holder) and (arms near10 plate near4 move)	US- PGPUB; UPAD	OR	OFF	2009/09/25 12:13
L2	2	(bath or reservoir) and (holder) and (arms near10 plate near4 movable)	US- PGPUB; UPAD	OR	OFF	2009/09/25 12:18
L3	O	(bath or reservoir) and (holder) and (arms near10 spring-biased near4 plate)	US- PGPUB; UPAD	OR	OFF	2009/09/25 12:23
L4	O	(bath or reservoir) and (holder) and (arms near20 spring-biased near20 plate)	US- PGPUB; UPAD	OR	OFF	2009/09/25 12:23
L5	О	(bath or reservoir) and (hold\$5) and (arms near20 spring-biased near20 plate)	US- PGPUB; UPAD	OR	OFF	2009/09/25 12:23
L6	4	(bath or reservoir) and (hold\$5) and (arm near20 spring- biased near20 plate)	US- PGPUB; UPAD	OR	ON	2009/09/25 12:23
L7	0	(bath or reservoir) and (hold\$5) and (arm near20 spring- biased near20 wetted near20 solder)	US- PGPUB; UPAD	OR	ON	2009/09/25 12:25

L8	0	(bath or reservoir) and (hold\$5) and (arm near20 spring- biased near20 wetted near20 solder)	US- PGPUB; UPAD	OR	OFF	2009/09/25 12:25
L9	0	(bath or reservoir) and (hold\$5) and (arms near20 spring-biased near20 wetted near20 solder)	US- PGPUB; UPAD	OR	OFF	2009/09/25 12:25
L10	0	(nozzle) and (hold \$5) and (arms near20 spring- biased near20 wetted near20 solder)	US- PGPUB; UPAD	OR	OFF	2009/09/25 12:25
L11	0	(nozzle) and (arms near20 spring- biased near20 wetted near20 solder)	US- PGPUB; UPAD	OR	OFF	2009/09/25 12:26
L12	0	(nozzle) and (arms near20 surfaces near20 wetted near20 solder)	US- PGPUB; UPAD	OR	OFF	2009/09/25 12:26
L13	57	(nozzle) and (arms near20 surfacenear20 wetted near20 solder)	US- PGPUB; UPAD	OR	ON	2009/09/25 12:26
L14	0	(nozzle) and (arms near20 surface near20 wetted near20 solder)	US- PGPUB; UPAD	OR	ON	2009/09/25 12:27
L15	11	(nozzle) and (arms near20 (rise or raise) wetted near20 member) and solder	US- PGPUB; UPAD	OR	ON	2009/09/25 12:29
L16	11	(nozzle) and (arms near20 (rise or raise) wetted near20 member) and solder	US- PGPUB; UPAD	OR	ON	2009/09/25 12:29

L17	0	(nozzle) and (member near20 (rise or raise) near40 wetted near20 surface) and solder and (holder near30 movable)	US- PGPUB; UPAD	OR	ON	2009/09/25 12:51
L18	O	(nozzle) and (member near20 (rise or raise) near40 wetted near20 surface) and solder and (holder near30 mov\$5)	US- PGPUB; UPAD	OR	ON	2009/09/25 12:51
L19	0	(nozzle) and (member near20 (rise or raise) near40 wetted near20 surface) and solder and (holder near30 mov\$5)	US- PGPUB; UPAD	OR	OFF	2009/09/25 12:51

$9/\ 25/\ 09\ 12:52:48\ PM$ C:\ Documents and Settings\ BLamb\ My Documents\ EAST\ Workspaces\ 10200072. wsp